


Targhee Pass Project - Design Issues for Alternatives

Entire Segment or Multiple Locations:

- * Shoulder Width too Narrow
- * Roadbase and Pavement Replacement Needed
- * Wildlife Migration/Connectivity
- * Slow Moving Vehicles in Eastbound Lane (Trucks, RVs)
- * Road Icing from Forest Canopy Shading
- * Blowing/drifting Snow
- * Trail Crossings, OHVs and Snowmobiles

0 0.5 1 2 3 4 Miles



Top of Pass:
* Trail Crossing
* Pullout

Howard Spring:
* Entrance and Exit from the Day Use Area
* Sub-surface Water

Issues at the Big Curve:
* Road Geometry
* Poor Drainage
* Forest Service Road Access

Bighorn Hills Estates:
* Existing and Planned Development
* Access
* Left-turn Movements